

Engine Gasket Sets - Cont.

CC	MODELS	YEAR	CYL	FULL SET	SUG. RETAIL
YAMAHA					
292	SM	1973	1 F/C	711134/B0721	\$21.60
292	SM	1974	1 F/C	711136/B0721	21.60
294	Enticer 300 C-H	1979-81/83-84	2 F/C	711138A/B5171	29.15
300	GP	1976	1 F/C	711030/B0721	21.60
300	GS	1976-77	1 F/C	711136/B0721	21.60
338	GP	1973-74	2 F/C	711139/B5171	29.15
338	SL	1974	2 F/C	711139/B5171	29.15
338	SL	1969-73	2 F/C	711029/B5171	29.15
338	GPX	1974-75	2 F/A	711100/B5171	29.15
338	GS	1975-78	2 F/C	711139/B5171	29.15
338	SL	1969-73	2 F/C	711029/B5171	29.15
338	Ovation	1989-90/92-99	2 F/C	711142C/B5171	29.15
338	SS	1969-70	2 F/C	711029/B5171	29.15
340	Enticer B-M, TM, TRM	1978-88	2 F/C	711142/B5171	29.15
340	Enticer 340 TG & TH & TF	1982-84	2 F/C	711142A/B5171	29.15
340	Enticer 340 TRN, TRP	1989-90	2 F/C	711142B/B5171	29.15
340	Excel E-M	1981-88	2 F/C	711142/B5171	29.15
340	Exciter	1976-78	2 F/C	711141/B5171	29.15
340	STX	1976-77	2 F/C	711141/B5171	29.15
340	SRX	1976	2 L/C	711139A/B5081	30.70
396	GP, SW	1971	2 F/C	711031/B5171	29.15
396	SL	1969	2 F/C	711036/B5171	29.15
396	SS	1969-70	2 F/C	711036/B5171	29.15
433	EL	1973	2 F/C	711144/B5171	29.15
433	EW, SW	1972-73	2 F/C	711144/B5171	29.15
433	GP	1972-73	2 F/C	711143/B5171	29.15
433	GP	1974-78	2 F/C	711146/B0671	29.90
433	GPX	1974-75	2 F/A	711101/B5171	29.15
433	SL	1972-74	2 F/C	711144/B5171	29.15
433	TL	1974	2 F/C	711144/B5171	29.15
433	TL	1975	2 F/C	711146/B0671	29.90
433	TW	1975	2 F/C	711144/B5171	29.15
433	Exciter	1976-78	2 F/C	711146/B0671	29.90
433	Exciter	1979-81	2 F/C	711146A/B0671	29.90
439	PR	1976-77	2 F/C	711146B/B0671	29.90
439	SRX	1976	2 L/C	711147A/B5991	33.90
439	SRX A-D	1977-80	2 L/C	711147B/B5081	30.70
439	SRX E	1981	2 L/C	711176/B0191	32.50
439	SS D-H	1980-84	2 F/C	711147C/B5171	29.15
439	SS	1985	2 F/C	711147F/B5171	29.15
439	STX	1976-77	2 L/C	711147/B5171	29.15
480	Phazer	1984-90	2 F/C	711168/B0671	29.90
480	Phazer	1991-98	2 F/C	711168B/B0671	29.90
480	Venture VT	1991-98	2 F/C	711168B/B0671	29.90
500	Phazer, Mt Lite	1999-01	2 F/C	711239/B0802	35.35
500	SX 500R	2000	2 L/C	711200/B5723	55.70
500	SX 500R	2001	2 L/C	711268/B5853	60.95
500	V-Max	1994-00	2 L/C	711200/B5723	55.70
500	V-Max, Deluxe	2001	2 L/C	711268/B5853	60.95
500	VT 500 Venture L/C	1997-00	2 L/C	711200/B5723	55.70
500	VT 500 Venture L/C	2001	2 L/C	711268/B5853	60.95
500	VT 500 Venture F/C	1999-00	2 F/C	711239/B0802	35.35
535	Excel V	1979-80/82	2 F/C	711147D/B5171	29.15
535	SRV	1980-81	2 F/C	711147D/B5171	29.15
535	SRV	1982-84	2 F/C	711167/B0671	29.90
535	SRV	1985-91	2 F/C	711167A/B0671	29.90
535	V-Max	1983-87	2 L/C	711140A/B0512	36.55
535	XL-V	1985-96	2 F/C	711147G/B5171	29.15
535	VK 540, II/III	1988-91, 93-02	2 F/C	711182/B0671	29.90
570	Exciter, LE	1987-90	2 L/C	711171/B5432	39.85
570	Exciter	1991-94	2 L/C	711171A/B5432	39.85
600	V-Max	1994-96	2 L/C	711201/B5723	55.70
600	V-Max	1997-99	2 L/C	711247/B0554	77.35
600	V-Max Deluxe/ER	1999-02	3 L/C	711240/B5148	143.05
600	Mt. Max	1998-99	2 L/C	711247/B0554	77.35
600	Mt. Max	2000-02	3 L/C	711240/B5148	143.05
600	SRX 600	1999	3 L/C	711242/B0954	78.00
600	SX 600R	2000-02	3 L/C	711240/B5148	143.05
600	VT 600 Venture	1997-98	2 L/C	711247/B0554	77.35
600	VT 600 Venture	1999-02	3 L/C	711240/B5148	143.05
700	SRX 700	1998-02	3 L/C	711246/B0914	71.25
700	SX 700R	2000-01	3 L/C	711241/B5148	143.05
700	SX Viper ER	2002	3 L/C	711269/B5148	143.05
700	Mt. Max	1997-02	3 L/C	711241/B5148	143.05
700	VT 700 Venture	1998-02	3 L/C	711241/B5148	143.05
700	V-max	1997-02	3 L/C	711241/B5148	143.05
743	V-Max	1992-94	4 L/C	711202/B0554	77.35
800	Mt. Max	1997	4 L/C	711243/B0554	77.35
800	V-Max	1995-97	4 L/C	711243/B0554	77.35